

Ian Gittens Consultancy Limited  
1 Colne Drive  
Berinsfield  
Oxford  
OX10 7PE  
4<sup>th</sup> March 2018

Mark Doodes Planning  
Unit 1, Wicklesham Lodge Business Park  
Faringdon  
Oxfordshire,  
SN7 7PN

Dear Mr Doodes

**Re: Church Place, Lydiard Millicent, Swindon Proposed Residential Development  
Road Safety Audit Stage 1- Items outside the scope of this road safety audit**

I enclose a copy of the Road Safety Audit for your information and action.

The Road Safety Audit Team would also like to draw to your attention potential issues which were identified and discussed during the audit. These are provided for your benefit and the Road Safety Audit Team in no way suggests that a full review of the highway environment has been undertaken beyond that necessary to undertake the Road Safety Audit as commissioned.

1. The road markings at Church Place junction with The Street are faded and in poor condition and should be re-laid.

If you have any further questions, please don't hesitate to contact me on the number below.

Yours sincerely



Ian Gittens  
Director  
Ian Gittens Consultancy Limited

Email address: [iangittens@iangittensconsultancy.com](mailto:iangittens@iangittensconsultancy.com)

C:\Users\iangi\OneDrive\IAN GITTENS CONSULTANCY LIMITED\UK Road Safety Audits\82-RSA Lydiard Swindon\Report\Issued\82-RSA-Stage 1 Church Place Lydiard Millicent Swindon- Items outside the scope V1.docx